

☐ UNCLASSIFIED ☒ CONFIDENTIAL ☐ SECRET (specify)
Approved For Release 2003/12/04 : CIA-RDP78B05171A000100010064-8

REQUEST TO PROCUREMENT DIVISION FOR SERVICES
(other than property or building maintenance and repairs)

OFFICE/DIV/BR NPIC/TSSG/RED	REQUEST NO. 5500-6067-70	DATE OF REQUEST	I CERTIFY AMOUNT OF [] THE ESTIMATED AVAILABLE CHARGE TO FAN 0155-5340 ARE 25X1
PROJECT TITLE Stereo Comparator C-in-S	PROJECT OR CONTACT OFFICER []	EXTENSION B [] R []	SIGNATURE OF BUDGET OFFICER [] DATE 59
CONTRACTOR (if known) []		PROPOSAL NO. AND DATE 21 October 1969	CONTRACT & TASK ORDER NO. (if known) [] 25X1

TYPE OF SERVICE REQUESTED		APPLICABLE ONLY TO REPAIRS AND MODIFICATIONS		
<input checked="" type="checkbox"/> RESEARCH/DEV	TRANSFER OF FUNDS TO OTHER GOVT. AGENCY (specify if applicable)	TECHNICAL INSPECTION IS REQUIRED BY		
<input type="checkbox"/> GRANT		<input type="checkbox"/> RECEIVING DEPOT T & I	<input type="checkbox"/> TECHNICAL MONITOR	
<input type="checkbox"/> REPAIR		<input type="checkbox"/> ITEMS TO BE PICKED UP OR <input type="checkbox"/> SERVICES PERFORMED AT:		
<input type="checkbox"/> MAINTENANCE		ITEMS TO BE REDELIVERED TO:		
<input type="checkbox"/> MODIFICATION				
STERILITY	CONTRACT CLASSIFICATION	WORK CLASSIFICATION	HARDWARE CLASSIFICATION	REPORTS CLASSIFICATION
<input checked="" type="checkbox"/> SC 0	CONFIDENTIAL	UNCLASSIFIED	UNCLASSIFIED	NONE
<input type="checkbox"/> SC 1				
<input type="checkbox"/> SC 2				

SHORT SUBSTANTIVE TITLE AND/OR DESCRIPTION OF SERVICE TO BE PERFORMED

Recondition an existing [] Model 5800 laser and Model 5801 power supply. This laser will be used as a standby laser for the laser-interferometer systems during the development and fabrication of a High Precision Stereo Comparator. This will be a change in scope to Contract [] 25X1

Declass Review by
NIMA/DOD

(See reverse for specific information
required on R&D requests.)

DESIGNATION		APPROVAL SIGNATURE	DATE

PROCUREMENT DIVISION USE			
DATE RECEIVED IN 12-30-69	RECORDED BY Mary	SECTION ASSIGNED TO WCPO	NEGOTIATOR Sent 12-30-69

25X1

21 October 1969

U. S. Government

Gentlemen:

25X1 A recent test of the [] laser located in the residual inventory showed it to be inoperative. Since at the present time there are no spare lasers available on the Stereocomparator program, in the event of a laser failure we would suffer a serious delay in delivering the equipment.

We therefore highly recommend that the Government authorize this unit be repaired and assigned as a standby laser for the Stereocomparator.

It should be noted that because of cable and connector differences, this laser, although similar, is not directly interchangeable with the present unit. However, it can be connected in a temporary manner and used as an emergency spare.

25X1 The [] has quoted a fixed price of []
25X1 for repair and recondition of the Model 5800 laser and 5801 power supply. The shipping charges are [] The total cost for the
25X1 repairs with G&A would be []

Your consideration and prompt attention to this request will be appreciated.

Very truly yours,

25X1 []
Administration Manager

BCJ/lab

5 Dec 1969

Bill,

Since the laser
in the attached quotation
is intended for use on
the development program
of the HPSC, I am
sending the quotation to
you for attention.

Ken K

CENTER ROUTING SLIP

FROM			DATE	
ESD/EPB			8 Dec 69	
TO	INITIALS	DATE	REMARKS	
DIRECTOR				
DEP/DIRECTOR				
EXEC/DIRECTOR				
SPECIAL ASST				
ASST TO DIR				
ASST TO DEP/DIR				
CH/PPBS				
DEP CH/PPBS				
EO/PPBS				
CH/IEG				
DEP CH/IEG				
EO/IEG				
CH/PSG				
DEP CH/PSG				
EO/PSG				
CH/TSSG				
DEP CH/TSSG				
EO/TSSG				
CH/SSD/TSSG				
PERSONNEL				
LOGISTICS				
TRAINING				
RECORDS MGT				
SECURITY				
FINANCE				
TSSG/RED	X			
DIR/IAS/DDI				
CH/DIAXX-4				
CH/DIAAP-9				
CH/PAO				